


There are two ways of storing Staron Sheets to avoid warping or sagging. Staron Sheets are most effectively stored at temperatures between 59 ~ 73°F (15 ~ 23°C ) and should be kept in a dry and well ventilated indoor area. Avoid exposure to moisture during storage. Staron Sheets should be stored flat and evenly supported as illustrated in.



*NOTE : Staron Sheets should be stored for easy access where Lot Numbers and Colors can be identified.*

Special care should be taken in storing Staron Sheets to prevent them from warping and sagging. Storage system, which allows easy accessibility, handling, and Lot identification, are the key. Exposure to moisture and direct sunlight during storage may damage the sheets. Staron Sheets should not be allowed to be stored in a wet environment.

*This Technical Bulletin is intended to provide guidelines for optimal fabrication, installation, and performance of Lotte Chemical Corp. products mentioned. Though the information contained herein is deemed reliable, none of the contents--including but not limited to the instructions, techniques, graphics, and recommendations--is to be understood as implying legal liability of fitness for a specific purpose, any other type of warranty, or being complete or absolute in its range and nature of information.*

*Depending on the user's particular application, all necessary measures must be taken to verify and test the adequacy for such needs or application. Any information or recommendation herein is strictly for purposes of reference and as such, Lotte Chemical Corp. assumes no responsibility for its suitability or accuracy or the use of such information for products other than Lotte Chemical Corp. Staron® solid surfaces & Radianz® quartz surfaces.*